PRE START INSPECTION

Make / Model: Kobelco - SK135SR-7 Registration: Northern Hire Group Membership: MELBOURNE TRACTORS PTY LTD

17 Nov 21 - 8:15 AM **Type:** Excavator - Medium (10 - 19.9 Tonne) **Serial Number:** YY09045983 **Created By:** Lachlan Rae

PRE START - FLUIDS			
Engine oil level OK COMMENTS:	Y	Ν	N/A
Hydraulic oil level OK COMMENTS:	Y	Ν	N/A
Coolant level OK COMMENTS:	Y	N	N/A
AdBlue level OK COMMENTS:	Υ	Ν	N/A
Fuel level OK COMMENTS:	Y	Ν	N/A
Machine free from major leaks to engine, cooling system, hydraulics, drive line etc. COMMENTS:	Y	Ν	N/A
PRE START - EXTERNAL INSPECTION			
Fire extinguisher is present & within inspection period COMMENTS:	Y	N	N/A
All lights and reflectors are present and serviceable (if fitted, machines without lights must only be used during daylight hours) COMMENTS:	Y	N	N/A
Amber safety beacon is fully functional COMMENTS:	Y	N	N/A
All hydraulic hoses are connected properly and free from leaks and damage (never use your hand to check for leaks, use wood or card board) COMMENTS:	Y	N	N/A
Hydraulic cylinder(s) free from leaks and damage COMMENTS:	Y	N	N/A
All batteries are constrained & fitted with a sturdily attached cover COMMENTS:	Y	N	N/A
All engine & exhaust guards are present, sturdily attached and free from damage COMMENTS:	Y	N	N/A
All tracks and track components are in safe working condition COMMENTS:	Y	N	N/A
Quick hitch (if fitted) fitted with locking pins, retainers & retention device in a safe working condition (consider excessive wear, cracks etc.) COMMENTS:	Y	N	N/A
All grease points present, functional and greased as per manufacturer's recommendations COMMENTS:	Y	N	N/A
All structural components are in safe working condition COMMENTS:	Y	N	N/A
PRE START - OPERATOR WORK AREA			
All operator access is non slip, sturdily attached and free from damage with three points of contact available COMMENTS:	Υ	N	N/A
Operator floor is non slip, free from damage & rubbish COMMENTS:	Y	N	N/A
All items in cabin/work area that could cause harm to the operator are securely restrained COMMENTS:	Y	N	N/A
Seat(s) sturdily attached and free from damage COMMENTS:	Y	N	N/A
Seat belt(s) present, sturdily attached and free from damage COMMENTS:	Y	N	N/A
Two mirrors fitted & fully functional (one on each side of machine) COMMENTS:	Υ	N	N/A
All windows and screens are present, clean and free from damage COMMENTS:	Y	Ν	N/A



PRE START INSPECTION

Make / Model: Kobelco - SK135SR-7 Registration: Northern Hire Group

Membership: MELBOURNE TRACTORS PTY LTD

17 Nov 21 - 8:15 AM **Type:** Excavator - Medium (10 - 19.9 Tonne) **Serial Number:** YY09045983 **Created By:** Lachlan Rae

Ν	N/A
Ν	N/A
Ν	N/A
Ν	N/A
Ν	N/A
Ν	N/A
Ν	N/A
Ν	N/A
N	N/A
Ν	N/A
Г	

